

Fresenius Medical Care North America Service Bulletin

Equipment: All Hemodialysis Machines

Bulletin: 15-FRS-001 Rev A

Subject: New Hardware

1.0 PURPOSE

To inform all Facilities, Field Service and Technical Support personnel of an additional tool required when working on newer 2008[®] Series Hemodialysis machines.

2.0 SCOPE

2008 Series Hemodialysis machines manufactured after September 2014 have a new screw that requires a Torx (T-20) screwdriver. These new Torx screws replace some of the Phillips Head screws used throughout the machine. Torx (T-20) screwdrivers are a common tool and can be purchased at a local hardware store.

Phillips Head Screw



New Torx Head Screw



If there are any questions regarding this bulletin, contact Fresenius Medical Care Technical Support at 800-227-2572

© 2015, Fresenius Medical Care North America, All rights reserved.